

## CASPIR Aircraft Record Cards

---

**Serial:** HB100

**Title:** Beechcraft Expeditor Mk. II serial:HB100 Aircraft Record

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** Taken on Strength: 1943-12-02. This accident involved 1 aircraft on 1944-January-16. Beechcraft Expeditor s/n HB100. This accident involved 4 people. Donkersley W, Flaherty JG, Pringle JTA, Sowerby E This accident had 4 fatalities. Squadron Leader Terence Alexander Pringle RAFVR Killed in Flying Accident service no:78022 Expeditor HB100, Flying Officer Ernest Sowerby RCAF Killed in Flying Accident service no:J/36500 Expeditor HB100, Flight Lieutenant Harry Woodward Donkersley RCAF Killed in Flying Accident service no:J/8203 Expeditor HB100, Squadron Leader James Gerard Flaherty RCAF Killed in Flying Accident service no:J/2826 Expeditor HB100

**Keywords:** Expeditor Mk. II,HB100,1943-December-02,Donkersley,Flaherty,Pringle,Sowerby

**Created:** 1943-12-02

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#HB100>

HC-100

BEECHCRAFT-HQ-45-B EXPEDITER I (WRITE-OFF)

1943

T F TRANSPORT.

5768

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

5.9.44. Aircraft lost en route to 32 O. T. U., 16.1.44, Touched to 3 R. D.  
in accordance with C. a. P. 16. Vol 1. para. 1396B.

