

HR 148

BEECHCRAFT UC-43-B EXPEDITER

1944

T E TRANSPORT.

5796 (43-35470)

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS' NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
27 Feb 48	1 see remarks	Orval James Bro.	app B		new. 1025556	1 May 49	AJC
8 Nov 51	2 reconditioning spec RB-1 modification PRM-27	MBA	CD W 511961				
10 May 54	3 Retighten main inspections	MBA	CD W 476816				
7 Jan 54	4 repair recommendation W.R. to P.						
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
21 May 57	B	Sea Island							
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Equipped with single cylinder type automatic pilot serv.
 27-2-48. For reconditioning and modification to Spec RB-1-5.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 293D - GM-1-43 (3029) H.Q. 885 - E-293

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>Stored Reserve - 7/46</i> DATE <i>18.2.44</i> TRANSFER ORDER No. <i>18673</i>			TRANSFERS <i>various</i>			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY			
<i>17.3.44</i>	<i>W.A. G.</i>	<i>T.O. 19223</i>	<i>7 Jan 55</i>	<i>W.R. MacLennan Park</i>	<i>QTO-837</i>			
<i>8.8.45</i>	<i>W.A. G.</i>	<i>TO 14388</i>	<i>7 Jan 55</i>	<i>SR W.R. MacLennan Park</i>	<i>QTO-837</i>			
<i>2.10.45</i>	<i>Stored Reserve WAC</i>	<i>T.O. 15234</i>	<i>8 Feb 55</i>	<i>W.R. MacLennan Park</i>	<i>QTO-437</i>			
<i>21-11-45</i>	<i>Stored Reserve MC (Abbotsford)</i>	<i>TO MC 15885</i>						
<i>Feb 1 46</i>	<i>Stored Reserve WAC (7R240)</i>	<i>Q 2069 (31.5-1)</i>						
<i>19 Feb 46</i>	<i>W.A. G. - (MacLennan Park)</i>	<i>T.O. MC 12802</i>						
<i>12 May 49</i>	<i>W.A. G. (412 Sgd)</i>	<i>TO 11199</i>						
<i>13/6</i>	<i>SR RD</i>	<i>TO 1493</i>						
<i>8 Nov 51</i>	<i>10TSU (MBA)</i>	<i>QTO 1285</i>						
<i>15 Feb 52</i>	<i>W.A. G.</i>	<i>QTO 1106</i>						
<i>16 May 54</i>	<i>10TSU (MBA)</i>	<i>QTO 564</i>						
<i>29 Sept 54</i>	<i>TC</i>							

REMARKS: U.S.A. No. 43-35470

2.10.45 - Serviceable

Crew Equip
C 0958 (EE 2448)
File 736 Misc 85
Leave - Lend

20 01 21 2
20 11 21 7

ENGINE TYPE	WASP R985-AN-31	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	USA 638	LEDGER FOLIO	714-Misc-USA 638	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.			
HB 148	37 BECHCRAFT UC-45-B EXPEDITER	1944	T E TRANSPORT.	5796 (43-35470)			

HB 148

EXPEDITER
3TWASP
R985-AN14B43-35470 2
5796

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE

QTO No.

TO

DATE

QTO No.

TO

8 Feb 55

QTO-437

Add the Sea Island

2 Jul 57

672

WR Linnell Park Slit-off

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS