

OVERHAUL DATA							
DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
15.5.42	Crash	Can Car + 7dy			1365.30	14.7.42	3TC
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD									
DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
6/6/41	1 "C"	Windsor Mills P6	0940	4EFTS. & A260	6/6	T/Lt. A.L. Ballantyne	1		
1.5.42	2 "B"	Windsor Mills	1810	4EFTS. A159	12/5	Sec. DM Watson			
3									
4									
5									
6									
7									
8									

B. S. LTD.
AIRCRAFT RECORD CARD
PAT'D 1920

REMARKS

Re acc. 1:- Eng installed: - Kenner BSR 1822/6468.
 Re acc 2: Eng install. - 1408/6072. On landing wing tip dug into ground and ac went over on its back. Caused by strong wind.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #12 Tech Detach. S.D.	DATE 19/6/40	TRANSFER ORDER No. 527			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
17/7/40	#3 Training Squadron	I.C. 710			
15.5.42	Can. Const Bdy	IC E211			
14.7	#3 T.C.	IC 1827			
8.10.43	#4 R.D. (W Res)	To 4423			
13.4.44	AFSAAL ...C.	F.O. 12517			
17-10-44	War Assets Corporation Charles & Barkley Co.,	20. 16661			

REMARKS

Hrs:-
since new 2690:10
" overhaul 1324:25

Cost.

Location:- ~~E.A.C.~~ 4 R.D. Scudoue B.C. A.T.P.

ENGINE TYPE	KINNER B5P	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	IP	4	LEDGER FOLIO	1200-38-3	SPECIFICATION No.	
REGISTRATION No.	MAKE & MODEL	YEAR	1940	TYPE	ELEM TRAINER	MANUFACTURERS No.	