

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
28.5.41	Crash	Fleet 9c			635.35	10.7.41	#1 T.C.
21.1.42	Crash	Fleet 9c			899.55	13.6.42	#3 J.C.
22.9.42	Crash	Low Airway				2.11.42	#3 T.C. S.R.
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
14/5/41	"B"	London City Airport	0905	#3 E.F.T.S. MT153	14/5	Lt. J. Foster	solo	Fleet 9c	10.7.41
15.1.42	"B"	Teulbee Stree.	1230	22 E.F.T.S. PA151	16/1	Lt. G.H. Cockburn	-	Fleet 9c	13.6.42
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re accident 1. -
4508 swung into 4702 (stationary) after landing.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT # <i>Training Command</i>	DATE <i>18, 7/40</i>	TRANSFER ORDER No. <i>857</i>			
TRANSFERS:		TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
28.5.41	Fleet 9c, Fort Erie	T.O. C169			
10.7	# 1 T.C.	T.O. 1617			
16.9	# 3 T.C. # 22 SFT	T.O. 2851			
21.1.42	Moordwyn 26A	T.O. F604			
13.6.	No. 3 JC	T.O. 1313			
12.9.42	Law Airways 21A	T.O. E851			
3.11.42	Stores Reserve #3TC	T.O. 3647			
2.12.42	# 9 R.D. (St. Res.)	T.O. 5692			
11.4.44	NDAS 13 T.O.	T.O. 12441			
17.10.44	WAR ASSETS CORPORATION FOR CHARLES H. BABB & CO.	T.O. 16663			

REMARKS

Hrs: Since New:- 1226:43
" Overhaul:- 4:30

Cost.

Location:- No. 3 T.C. 9 R.D. B.C.A.T.P.
St. John's Ave.

ENGINE TYPE	KINNER B5R	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	4	LEDGER FOLIO	1200-38-3	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL	SOLD	YEAR	1940	TYPE	ELEM TRAINER	MANUFACTURERS No.