

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
26.5.42	Time exp.	Fleet Aircraft				2.7.42	#320
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	#REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
8.9.41	C	London Ent.	1000	TEFTS SA70	8/9	W. R. N. Macdonald	1		
8.1.42	C	London Ent.	1430	TEFTS A.4	8/11	Sac. H. Swin			
2.8.42	C2	Main Aerodrome	1630	13 EFTS SE117	2/8	Sac. J. B. H. Lamin	Solo		
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

2.12.43: Allotted to #9 R. U. (w. res.) pending write off action.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>Storage Reserve London</i>	DATE <i>18/1/46</i>	TRANSFER ORDER No. <i>2103</i>			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>12/19/40</i>	<i>#1 Training Command</i>	<i>T.O. 2316</i>			
<i>26.5.42</i>	<i>Fleet Aircraft Section</i>	<i>T.O.C-470</i>			
<i>2.7.</i>	<i>#37C</i>	<i>T.O. 1497</i>			
<i>16.9.43</i>	<i>Storage Reserve #9 R.D.</i>	<i>T.O. E1258</i>			
<i>9.12.43</i>	<i>#9 R.D. (w. res.)</i>	<i>T.O. 5696</i>			
<i>11.4.44</i>	<i>APDAL #3 T.O.</i>	<i>T.O. 12442</i>			
<i>17.10.44</i>	<i>WAR ASSETS CORPORATION FOR CHARLES H. BABB &amp; CO.</i>	<i>T.O. 16663</i>			

REMARKS

Hrs: Since New:- 1263:10  
" Overhaul:- N.A.

Cost.

Location:- ~~No 3 T.C.~~ *9 R.D. B.C.A.T.P.*  
*St. Johns Que*

ENGINE TYPE <i>KYNER 85R</i>	UNITS <i>1</i>	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH <i>TP 4</i>	LEDGER FOLIO <i>1200-38-3</i>	SPECIFICATION No.
REGISTRATION No.	MAKE & MODEL <i>SOLD</i>	YEAR <i>1940</i>	TYPE <i>ELEM TRAINER</i>
			MANUFACTURERS No.