

4564

FINCH II

(WRITE-OFF)

1940

ELEM TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | | | | | | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | # REPORT | REFERENCE | DATE | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL | DATE SERV. |
|---------|----------|----------------------|------|----------|-------------|------|----------------------|-------------|-----------|------------|
| 18.8.41 | 1 C3' | Acronia Township Ont | 1515 | 9 | EFTS, s A94 | 20/8 | Sgt M. D. Moffatt | 2 | | |
| 19.9 | 2 "A" | Niagara Township | 1040 | 9 | EFTS, s A98 | 19/9 | Sgt. F. A. Smith | | Write-off | |
| 3 | | | | | | | | | | |
| 4 | | | | | | | | | | |
| 5 | | | | | | | | | | |
| 6 | | | | | | | | | | |
| 7 | | | | | | | | | | |
| 8 | | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 2: 2% spun into high tension wires and took fire.
 Total Flying Time - 824²⁰ hrs (ault " I.T.C. letter, 926-22-1, d. 22/9/42.

