

4704	FINCH II	SOLD	1940	ELEM TRAINER	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.	

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
29/5/41	"A"	Windsor, Ont	0945	#9EFTS, 2 A29	29/5	LAC H.T.C. [unclear]			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc: Finch 4707 and not 4704 involved in this accident.
 Authority: # I.T.C. letter file 1100-47-4, 8/7/41
 3. 11. 43. Allotted to #9 R.D. St. Johns (W. Res.) for write off action.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #1 T.C. Toronto	DATE 20/11/40	TRANSFER ORDER No. 5202			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
5.4.41	Stored Reserve #3 T.C.	T.O. 79			
23.4	RCAF Stn Rockcliff	T.O. 352			
12.7	#1 T.C. Trenton	T.O. 1689			
5.1.42	#3 T.C.	T.O. 13121			
16.7.42	Patterson & Hill	T.O. E.555			
1.10.	Stored Reserve #3 T.C.	T.O. 3040			
25.2.43	#3 T.C. 20/11/40	T.O. 5829			
3.11.43	#9 R.D. St. John's (W. Rec)	T.O. E.1513			
11.4.44	APDAL #3 T.C.	T.O. 12650			
4.10.44	Wing Supply Corporation Charles H. Sault & Co.,	T.O. 16666			

REMARKS

Hrs: Since New:- 2167:00
" overhaul:- 854:20

Purchased

Location:- No 3 T.C. 9 R.D. St. John's Que

ENGINE TYPE	QUANT. REC	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	TP 4	LEDGER FOLIO 1200-38-3	SPECIFICATION No.
REGISTRATION No. 4708	MAKE & MODEL	SOLD	YEAR 1940	TYPE ELEM TRAINER
				MANUFACTURERS No.