

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1.8.42	crashed	Stanley + Fry				25.11.42	EAC SR
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
5.9.41	"C14"	Stanley Airport	0940	#17EFTS 5T83	5/9	LAC. J. Jones	2		
28.1.42	"B"	Stanley Airport	1245	17EFTS 5T152	22/11	S/P. Cook DJ	1		
29.6	"C2"	Stanley Airport	1150	17EFTS 5T239	29/6	Pac J. Paquet	Solo		
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

By Acc. 2:- Eng. installed # 6261  
 Re. Acc. 3:- Left wing struck ground causing ground loop  
 22.11.43: allocated to #4 Rtd. (w. ins) Seabone pending disposal

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREWS (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #3 Training Command	DATE 28/1/41	TRANSFER ORDER No. 5940
------------------------------------	--------------	-------------------------

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
1.3.42	San. Lav + Dry 10/8	T.O. E 63			
2.5.11	Sp. Reserve EAC <sup>1/2</sup>	T.O. 4213			
2.3.43	Stand Reserve #3 T.C. B. 3	T.O. 5886			
19.5.	#3 TC (#17 EFTS) 11/1	T.O. 1094			
23.11.43	#4 S. A. (w. red.) Scoudouc	T.O. 5003			
13-4-44	E.A.C. - Apdal	T.O. 12519			
1/10-44	Wax Assets Corporation Charles H. Bolt & Co.,	T.O. 16661			

REMARKS

Hours:-  
 Since New:- 421: 20. Purchased  
 " overhaul Nil.  
 Location:- E.A.C.  
 4 R.D. Scoudouc

ENGINE TYPE	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO 1280-20-3	SPECIFICATION No.
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE
	SGLD	1941	ELEM. TRAINER
			MANUFACTURERS No.