

9639

HELICOPTER
H21BWRIGHT
R1820-103

CFJTR

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
8 June 56	633	ATC 108 Com 2nd Pool	8 Aug 66	QT0335	Skystar wld ampriev CR
5 Aug 57	766	Vertol A/C CR	8 Aug 66	QT0338	ATC 102 KV Trenton
22 Oct 57	480	Spaslan Air Services AD	25 Jul 68	R01H4	ATC 424 CR Trenton
28 Sept 59	643	Vertol Aircraft CR #1	21 Apr 69	QT0128	ADG 25B Chatham (519083)
5 Oct 60	607	ADG str Chatham	6 Aug 69	QT0271	ATC (H+R) ^{H21} str Trenton (519093)
7 Nov 61	ADG QT051	ADG str Cold Lake	17 Oct 69	QT0381	Skystar wld ampriev (519083)
20 Mar 62	ADG QT06	ADG str Chatham	17 Oct 69	QT0381	ATC 424 (H+R) str Trenton
18 Apr 62	174	UTSA Vertol CR/ampriev	11 June 70	QT0210	ADG ⁵²⁴ Chatham (519083)
18 Apr 62	174	ADG str Chatham	9 Aug 71	ADG QT027	ADG 25B Baginville (H34629)
20 Oct 64	QT0685	ATC 102 KV Trenton	14 Oct 71	QT0348	IRAMOUAL str Trenton (434629)
24 Sep 65	QT0494	Skystar Ampriev CR	12 Jan 72	QT0459	ghd str DU str Trenton (434629)
24 Sep 65	QT0494	ATC-102 KV Trenton			ME 3006

Built by Vertol

OVERHAUL DATA

9659

DATE	QTO No.	CONTRACTOR		REPAIRS
6 Aug 57	766	11750	572814	for embodiment of mods as per Fed. file letter 57C 1120 10 May 57 Alternative B
28 Sep 59	643	11750	(772813) (979815)	for repairs, to be brought up to SFR Configuration in accordance with letter 0384P-3 to RPL 440 all outstanding special inspections and 6A made again
18 Apr 62	174	Nertal	179844	install floatation gear & mod rescue ^{systems} para to effect repairs and reconditioning as per work package
24 Sep 65	494	Hydrate Am	579844	Installation floatation gear.
8 Aug 66	338	Hydrate Std	579844	Aircraft sampling inspection
17 Oct 69	Q10381	Hydrate Std	579844	

