

1345

HARVARD I

(WRITE-OFF)

1939

S. E. TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
3.10.41	Crash	Moorduyen					Spares & produce
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
8/2/40	"D"	30 Mi. S. E. Drenton		C.B. 518	8/2				
3/8	"C4"	E.T.S. Borden	1625	C.B. 2631	3/8				
15.9.41	"B"	Drenton Aero/d.	1115	C.F.S. s A 924	15/9	Sgt. S. J. Frederick		Moorduyen	
4	"B"								
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. Acc. 3: - Very strong gusty wind. a/c stalled, and crashed on landing

