

2623

HARVARD III

(WRITE-OFF)

1940

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2/2/41	"C2"	Camp Borden	1245	1527S Sig C22	2/2	LAC H.G. GOSMAN	1		
24.4.41	"C1"	Camp Borden	1000	1527S Sig G57	24/4	F/L B.C. Andrew	1		
12.6.41	"C1"	Camp Borden	0350	C.B. sig C102	12/6	P/O W.W. Selman	1		
24.2.42	"A"	Run 8 Camp Borden	1500	1527S A 310	24/2	Lac W.J. Hogan		Washed	24
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc. 4 - Eng. installed PD26/ H109. Mid air collision between this ac and ac Yale 3373.

