

2631

HARVARD 11

(WRITE-OFF)

1940

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
19.6.41	1 Crash	Moordwyn				28.8.41	# 3T.C
21.7.42	2 Crash	Moordwyn					
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
12/16/41	1 "B"	Uplands Ont.	2359	#2 SFTS A485	13/6	LAC G. S. Reid		Moordwyn	28/8
12.1.42	2 "C"	St. Hubert Aerod.	0840	13 SFTS A124	12/1	LAC J. M. McCullum Solo			
3.2.	3 "C"	St. Hubert aerod.	1400	13 SFTS S. A150	3/2	LAC T. J. Sugna Solo			
4									
5									
6									
7									
8									

D. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc 1:- 9c overturned after landing when pilot swerved sharply to avoid pupet taking another aircraft across runway without permission.

Re Acc 2:- Engine installed - Prop S3H-1 no. 5070/10603.

