

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1.5.41	1	Uplands Ont	0215	2SFTS s A394	1/5	Sgt R M Davidge			
19.11	2	Uplands Aerod	2110	2SFTS s A646	20/11	1st Lt HA Brennan			
12.2.42	3	Cobden. Ont	1000	2SFTS s A.704	12/2	1st Lt Ed. J. Jones	Solo	Write-off	
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re Acc 1: - Harvard 2687 taxied into rear of Harvard 2661  
 Re acc 2: - Eng. installed - Prop 53H-1 - no. 7218/1257  
 Re Acc. 3. Eng. installed 8556/4409 Cause obscure.  
 Acc. After signed by Wg. Comdr 2<sup>nd</sup> Brien from Uplands 24/2/42  
 Court of inquiry being convened. file 1100 - 26 - 61

