

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
12.3.41	Accident	Noorduyne				10.7.41	# 3 T.C
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
19/2/40	"C"	Edwards Field	0920	#28378 Sig 1157	19/12	310. 21. B.M. Burns	1		
6/3/41	"B"	Navan, Ont	1015	#28378 Sig 1157	6/3	310. B.N.B. Jenkins	1	Noorduyne	10.7.41
15.8	"A"	3mi. W. of Upwards	0820	2SFTS	15/8	LAC. H.W. Long		Spares & produce	
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc 1. - Landed with undercarriage up.
 Re. acc 3, Signal # 25715 1100-26-89, 850-L-28
 Aircraft crash after take-off. (flew into earth)
 Total Flying Time: 16.1⁰⁰ hrs (auth. Log Book)

