

2792

HARVARD III

5-1-D

1941

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
21.4.43	Time exp.	Aircraft Repair				26.8.48	# 4-TC
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
12/3/41	1	"C2"	Moose Jaw	1350	#32 SFTS s A408	13/3			
26.8	2	"C3"	Moose Jaw, Aero/d	1500	#32 SFTS s A408	27/8	LAC. R. Wolstenhulme		
11. 11	3	"C3"	Moose Jaw, Aero/d	1930	32 SFTS s A881	12/11	LAC. B.A.J. Bonetta		
	4								
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT. D. 1920

REMARKS

Re Acc. 1. - Harvard 2643 taxiing out, struck stationary Gc 2792.
Wasp S3H-1 engine installed 7775/4015

