

2799

HARVARD II

(WRITE-OFF)

1941

S. E. TRAINER

REGISTRATION NO.:

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
11/7/41	"A."	Boharm	1030	#325FIS, SA229	11/7	D.J. Underwood		Spares + produce	

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc. - stalled while doing precautionary landings,
and crashed & caught fire
Engine installed - Prop 53H1 - no. 8467/4326.

