

2812

HARVARD 111

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
24.4.41	1 "C7"	Camp Borden	1010	#1SFTS, & C56	24/4	F/O C. Raymond	1		
31.5.41	2 "C1"	Camp Borden	1500	#1SFTS, & A145	31/5	Lt C. W. T. Millam			
27.6	3 "C2"	Camp Borden, Ont.	1000	#1SFTS & C110	27/6	LAC. B. W. Andrews	1		
25.11	4 "B"	Rt Edenwale	0230	#1SFTS & C185	26/11	LAC. H. E. Waters	Solo		
25.4.42	5 "A"	8m S. Mt View	1630	C7S & A540	3/5	Sgt H. Brown	1	WRITE-OFF	
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc. 1: - Harvard 2705 ground-looped off runway and collided with Harvard 2812

Re acc. 5: - Eng installed 4988 % spiralled & dived into ground

