





REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
15/10/43		Noorduyn Aviation				12,444	# 1 TC
10 Dec 46	Conditioning in C.A. at 4000	Com. Car. Shop	app A-1015			87m 41	SAC
3	Rm-1-c						
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
16-4-44	1 "C1"	Dummerle, Ont	1430	6 SFTS, 2	17/4	P/O J.R. Youngs	1		
15/5	2 "C3"	Kaplan Aerodrome	1410	6 SFTS, Sig A277	16/5	P.A.C. Agnew			
18.11.	3 "C1"	Holland Aerod	1930	6 SFTS, S A546	19/11	P.A.C. R. Sanford			
5/10/47	4 E	4244 km Hamilton	1550	A4	2/10	P.O. R. Smith	Eng	3152/2623	17
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT. D. 1020

## REMARKS

18-9-45 Allotted to Mob Repair Depot (U.R.) for ATR II (Cessna) Installation  
 1 Apr 46 - Converted to ATR II on TO. MC. 12010 d. 1 Apr 46  
 16 Sept 47 - A/c No. T.S. 7 - 4034.10, T.S. O. 1228.30. Fitment - Sld.  
 31 Dec 47 - A/c No. T.S. 7 - 4064.40, T.S. O. 1269.05; Condition (Risk - Vietnam) Sld.  
 25 Mar 48 - " " " " 4084.50 - 1289.10  
 21 Sept 48 - C.A.C. 2 - 1026 BG (50 Sept 42 P) on 1038 BG-2.8, not modified to 5-11-60/17  
 T.S. N. 4168.65, T.S. O. 1378.70  
 A/c allotted to PAR for mods EO-05-55A-6B/14 and 6B/15 (Tail wheel de-  
 clatching and electrical junction box) A/c No. 406314 d. 21 Dec 50.  
 1003 TSO 593 31 Jan 57 A/c has radio compass installed

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

## AIRCRAFT RECORD CARD

FIRST ENTRY AT #1 Training Command DATE 25/1/41 TRANSFER ORDER No. 5906

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
15/10/43	Noorduyn Aviation	T.O. C.1843			
12.4.44	4 ITC (16 B.F.T.D)	To 12387			
15.1.45	No. 1 A.C.	T.O. 17863 (G31)			
18.9.45	U.S. No. 6 Repair Depot	To 6.288			
3/2/45	<del>SR MC (4 REMUP)</del>	<del>To MC 12010</del>			
16 Apr 46	SR MC (4 REMUP)	To MC 12010			
11 Oct 46	70 V.A.C (4 REMUP)	To MC 13115			
	In Millin				
10 Dec 48	70 V.A.C (4 REMUP)	To MC 12519			
8 Mar 49	C.A.C (CXS)	To MC 12707			
14 May 56	Serviceable Reserve Co. P	OTO 710			
17 Mar 57	Serviceable Reserve Co. P	OTO 855			

REMARKS

1 Apr 46 - Conversion to ATR II  
 15.1.41 - hand from North American Aviation  
 Rf no 58/90

U.K. Contribution

ENGINE TYPE WASP 33H-1 UNITS 1 AIRSCREW TYPE (CODE) REF No 6545

BATCH No QUAN IN BATCH TR 143 LEDGER FOLIO 1200-38-6 SPECIFICATION No 4582

REGISTRATION No MAKE &amp; MODEL YEAR TYPE MANUFACTURERS No

2822 X

HARVARD II

1941

S.E. TRAINER

Harvard ATR II