

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
22/2/41	"C"	Charlottesville	1825	# 314 RSP, A22	22/2	2 nd Lt. B.A. Lovett			
10-4-41	"C ₃ "	Summerside, P.E.I.	2300	9SFTS, s A 248	11/4	P/O J. S. Shovel	1		
17-6	"C ₁ "	S' Side, Aero Id	3215	9SFTS, s A 446	18/6	Lt. C. M. Zambler			
18-11	"A"	Charlottesville P.H.	1650	9SFTS, s A 2	18/11	Lt. S. M. Lewis		Write-off	
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc. 1 - Category C₁ - Spoke \$32 from #37.C.
 Re Acc. 2 - Aircraft 2864 taxied into Harvard 198: damaged wing of 2864 and middle of 198.
 Re Acc. #4 - 7c reported to have been spun into water - pilot missing, but believed still in aircraft.

