

2919

HARVARD 11

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS' NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N. NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
22.1.42		#6 R D Trenton				19.2.42	SR T.C.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
31.3.41	1	Dauphin coast	1445	10 SFTS sig.	1/4	LAC T. Carver	-		
30.5.	2	Dauphin Man	1100	10 SFTS, SA 25	30/5	Sgt. W. H. Hicks	1.		
6.1.42	3	Sydney Township	1740	2 SFTS SA 674	7/1	LAC R. J. Evans	-	#6 RJD	2.3.42
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 1: - Motor failed on take-off.

17/1/42: - Allotted #1 T.C. for salvage operations.

Re acc 3: - Engine installed - Wasp S3H-1 No 8691/4452

Also crash also reported by CFS Trenton SA 47. 7/1/42

Re 9/21 - Allotted #1 T.C. 2/3/42

