

2961

HARVARD 11

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
31.3.43		hoordun, Av.				14.6.43	17.C. (SR)
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
13.5.42	C2	Trenton Aerod	1615	CAS SA 585	14/5	Plt J W Cowling	1		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc 1:- Pilot of this Gc failed to see Gc Crane 7997 on landing path and collided with it.

31.5.44 Allocated to # 6 S.W. (w.res) for strike off action & reduced spares & produce.

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
#68248 E135 E 101	7.25.44	1038 B9 (290)		H G R D	H G R D (10.100.)	13.6.44	6-106

DISPOSAL PARTICULARS

AIRFRAME <i>spares &amp; produce</i>	T. O. No. 6-106
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF CU R-1589

## AIRCRAFT RECORD CARD

FIRST ENTRY AT		DATE	TRANSFER ORDER No.		
<i>Mo. D. C. Toronto</i>		<i>17/3/41</i>	<i>6516</i>		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>31.3.43</i>	<i>Woodbury Av. #4</i>	<i>T.O. C 3094</i>			
<i>14.6.43</i>	<i>Stored Reserve #1 T.C. 1316</i>	<i>T.O. 1586</i>			
<i>26.8.43</i>	<i>#1 T.C.</i>	<i>T.O. 3304</i>			
<i>31.5.44</i>	<i>#6 R.D. Lines Trenton</i>	<i>T.O. C 358</i>			
<i>13.6.44</i>	<i>Spares &amp; produce</i>	<i>T.O. 6-106</i>			

REMARKS

ENGINE TYPE WASP S3H-1 UNITS | AIRSCREW TYPE (CODE) REF. No.

BATCH No. QUAN. IN BATCH TP. 143 LEDGER FOLIO 1200-38-6 SPECIFICATION No.

REGISTRATION No. 2961 MAKE &amp; MODEL HARVARD 11 (WRITE-OFF) YEAR 1941 TYPE S E TRAINER MANUFACTURERS No.