

3020

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1    |        |         |           |      |                 |                |           |
| 2    |        |         |           |      |                 |                |           |
| 3    |        |         |           |      |                 |                |           |
| 4    |        |         |           |      |                 |                |           |
| 5    |        |         |           |      |                 |                |           |
| 6    |        |         |           |      |                 |                |           |
| 7    |        |         |           |      |                 |                |           |
| 8    |        |         |           |      |                 |                |           |
| 9    |        |         |           |      |                 |                |           |
| 10   |        |         |           |      |                 |                |           |
| 11   |        |         |           |      |                 |                |           |
| 12   |        |         |           |      |                 |                |           |

## ACCIDENT RECORD

| DATE     | CATEGORY | PLACE               | TIME | REPORT REFERENCE | DATE  | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL         | DATE SERV. |
|----------|----------|---------------------|------|------------------|-------|----------------------|-------------|------------------|------------|
| 17.11.41 | A        | 2 m W Chrysler Ind. | 1700 | 2, SFTS, SA644   | 18/11 | Lie. P.A. Jait       | 1           | Spares & Produce |            |
| 15.6.    | C4       | Dauphin Aerod.      | 0145 | 10, SFTS, SA335  | 15/6  | W.B.S. Beall         | 1           |                  |            |
| 3        |          |                     |      |                  |       |                      |             |                  |            |
| 4        |          |                     |      |                  |       |                      |             |                  |            |
| 5        |          |                     |      |                  |       |                      |             |                  |            |
| 6        |          |                     |      |                  |       |                      |             |                  |            |
| 7        |          |                     |      |                  |       |                      |             |                  |            |
| 8        |          |                     |      |                  |       |                      |             |                  |            |

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc 2: - % crashed; cause obscure. Pilot and crew member Lieut  
 J.D. Miles both killed. Eng. installed - Asp S3H-1 no. 9076/4635

Re acc 4: - Ref. for registration numbers - 2 TC letters, 17.1.42 on file 1021-4-1.  
 Engine installed - Asp S3H-1 no. 9076/4635.

