

3048

HARVARD 11A

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
29.1.43	Time exp	Moore design				3.4.43	S.R. # 3T.C.
28 Sept 48	reconditioning - mod. & CB in 1924	Camel Car City	spare Apr 46		3064.15 1150.50	22 Dec 49	<PO
8 Apr 54	complete reconditioning see A-1	AOT	C-10 W 511963				
26 Sept	for necessary repairs take wheel w/R to P					9 Dec 55	LN 10
	ad clutching installation						
	EO 05-55A-CR/144						
	adder & electric junction						
	has mod EO 05-55A-CR/144						

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

28.8.47 - intercom communication installation only 6 KD. 24.6.46.89
 on 500.1.3
 6 Apr 48 - 800 ft gear mod. 3064.15 mod. 1150.50 Production Dept. 22 Dec 49
 31 Mar 49 - 10 Apr 49 - 3185.35; 530.124.15

