

3093

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
17.9.41	"C1"	Ayleron Crk A.	1515	145435 SA51	18/9	LAC H. Gooden	1		
11.12	"C2"	Ayleron Crk.	1145	145715 SA132	11/12	P/O M. B. Haskins	1		
30.1.42	"C1"	10m SE Ayleron Crk.	1320	145715 SA27		LAC M. J. Bradshaw	1		
28.4.	"A"	2m E Ayleron Crk.	0320	145715 SA111	28/4	LAC R. A. Welsh		WRITE-OFF	
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc 2 - Shuttle jammed and engine caught fire.  
 Re acc 4 - Eng installed, 213527 Night flying. AC struck  
 ground and burned.

