

3086

HARVARD II A

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
18 Dec 41	see remarks	Cr C Jky	app B 26625		new 2850.00 old 21/1	30 Oct 49	DC SR6A
4 Aug 44		Cr C Jky					
29 May 56	for replacement of S. 20-25	ALL	572762			29 May 56	R CD
	LESR 6B/140						
	6B/15						
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2.10.41	C3"	Oxley Aerod	1012	14 SFTS S A63	2/10	Sac. K.W. Noble			
12.1.42	C1"	Kingal		14 SFTS S A.4	12/1	WAR J.L. Lang	Solo		
6.3.42	C1"	Oxley Aerod	1310	14 SFTS S A56	7/3	RAC DR Cuthbertson			
19.3.42	C"	Oxley Aerod.	0845	14 SFTS S A73	25/3	3/D AW. Metler	1		
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

680's - 24-6-7689. 28 Aug 42 over 500-1-3. (ATR.5 installation complete)
 original time - 2850.00, condition good.
 18 Dec 41 - 274 made before 2/10/41 RM-17 and reconditioning to
 spec. R. 11.
 4 Jan 48 - a page 7571 - 2850.00, 140 H.A. Condition Fair. 7/3/48. Set
 19 Mar 42 - 2855.55, - 50. 210 H.A. Fixed fittings only. all ornaments:
 31 Mar 49 - a page 7571 - 3034.00, 750 178.05'

