

3111

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|---------|-----------|----------|-----------|------|-----------------|----------------|-----------|
| 18.3.42 | Collision | Moorduin | | | | 16.5.42 | "3 T.C |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | No. IN CREW | DISPOSAL | DATE SERV. |
|----------|----------|----------------|------|------------------|-------|----------------------|-------------|----------|------------|
| 29.10.41 | "C1" | Trenton Aerod | 2245 | C.F.S. 5297 | 29/10 | PO J. James | 1 | | |
| 18.2.42 | "C2" | Trenton Aerod. | 1140 | C.F.S. SA 999 | 20/2 | PO A. Smith | Solo. | | |
| 23.2. | C | Trenton Aerod. | 1625 | C.F.S. SA 10 | 23/2 | J. H. Oakes | 1 | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 3. Collision on ground between this ac and Harvard 2955.

