

3228

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N'NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
8.11.41	Crash	Moordungh				2.2.42	#3 T.C
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
29.9.41	1	"B" Pictou Aerod.	1225	C.T.S. s A147	29/9	PO17 Krueger		Moordungh	2.2.42
2.6.42	2	Moncton Aerod	0300	88235 s A522	2/6	Plac C Whymen			
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc. 1. - C.T.S. s A168, 27.10.41 amends crash cat to "B" from "C",  
 eng installed 9/5/41 / 14/6/41

Re acc. 2. When waiting to take off at night was struck by Harvard 3014

