

3269

HARVARD II

(WRITE-OFF)

1942

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
25.3.42	"C"	Weymouth Aerod.	10.55	14577SSA74	26/3	CAC H A Lotimer			
26.5	"B"	Weymouth Aerod.	02.30	14577SSA128	27/5	P/O C Garsnell	1		
13.7.	"A"	Weymouth Aerod.	09.39	14577SSA169	13/7	P/O B D Hughes	1	FLY R.D.	Weymouth Aerod. 00
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 2. Eng. inst. 4844, ac swerved and ground looped when being landed by pupil pilot.

Re. acc. 3:- ac spun and dove into ground. Cause obscure.

