

3762

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
23/42	C1	Monter Aerod	1030	B S FTS A48	23/1	Lieut. A. Henderson			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc. 1: Harvard 3022 skidded into Harvard 3762 while taxiing. Eng. installed: Hesp. S.3H-1 no. 9047/4606

