

3792

HARVARD 11

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
6.7.43	1	Line Ely	Roordun Av			30.9.43	#3TC(SR)
8.11.50	2	reconditioned par m-6	nw d	W501660		21.4.51	JB
	3						
	4						
	5						
	6						
	7						
	8						
	9						
	10						
	11						
	12						

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
	1								
	2								
	3								
	4								
	5								
	6								
	7								
	8								

B.S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

9.10.45 Installation of ATR II Equipment
 1038/B6 (C.E.U) d 14 July 47 on 1038/B6-1-8 off U.S.A - 2512.55 : 55.0.1005.40
 By " 1597.05 " 20.40.

10 RD-10-24 d 29 Aug on 1038/B6-2-7 - contains ATR II and AR 15 equipment

