

AH 196

HARVARD II

TRANSFERRED FROM R.A.F. (WRITE-OFF) 1940

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
24/1/41	C2	Summerside	1550	# 9 S.I. Log 926	24/1	Flt Lt B.P. Johnson	1		
1.6.41	"A"	Lawendish P.E.I.	1545	# 9 SFTS, & A398	2/6	Flt Lt B.M.C. Fletcher	1	Write-off	
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Reasel:- 9% burned.

Total Flying Time:- 3830 hrs (auth Log Book)

