

AJ 595

*

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
31.7.41	1 Done & up	Boarding Aviation					
	2						
	3						
	4						
	5						
	6						
	7						
	8						
	9						
	10						
	11						
	12						

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
11.10.41	1 C5	Kingston Aerod.	1520	315FTS STC 169	12.10	ALA Payne			
25.6.42	2 C1	Kingston Aerod	1630	3187JS SC 113	25/6	ALA C. Plummer			
	3								
	4								
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 1 - a/c A1595 while taxiing preparatory to take-off was taxied into by a/c A1658
 Re acc 2. When taxiing the driver braking to avoid collision caused
 a/c to stand out nose

