

AJ-762

HARVARD II

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
23.9.43	1 Time Exp	Aircraft Repair				24.11.43	S.R.#4TC
8.11.50	2 <del>Time Exp</del> mod of P.M. 4-6	W.W. 2	W501660				
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
13.6.42	"C14"	Swift Current	0830	39/2255 A678	13/6	Capt Clifton			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re. acc. 1 - Collision between this Yc and Yc Harvard II AJ 760  
 10KJ - 10 2856/CE on <sup>17/4/47</sup> 31-3-10. over 2500 hrs. flying time since m.I.T. 50. 1083.20

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

## AIRCRAFT RECORD CARD

FIRST ENTRY AT *Stored Reserve #4TC* DATE *16.10.41* TRANSFER ORDER No. *3227*

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
18.10.41	#4TC	#34SETS T.O. 3279			
23.9.43	Aircraft Repair. Edm.	To F-1229			
24.11.43	Stored Reserve #4TC	To 5392			
22.12.42	#4TC	T.O. 6184			
1-12-44	NO. 2 A.C.	T.O. 17328 (30)			
11.4.45	STORED RESERVE No. 2 A.C.	T.O. 12241			
9.10.46	Workshop Repair #1010	T.O. 15343			
	WR. MC RD TO MC I5920				
3/2/46	SR: MC: (10 R.D)	To MC 16348			
8/1/50	Q11501 (220)	To 1396			
June 51	JL	To 1134			
1/1/54	SR 25AMB	QTO 1838			

REMARKS 7-7-45:- STORED RESERVE - FROZEN SERIES

*U.K. contribution*ENGINE TYPE *WASP S3H-1* UNITS *1* AIRSCREW TYPE (CODE) REF. No. *14912*

BATCH NO.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.
REGISTRATION No. <i>AJ-762</i>	MAKE & MODEL <i>HARVARD T1</i>	YEAR <i>1941</i>	TYPE <i>STE TRAINER</i>
	<i>S.R. 25AMB</i>		MANUFACTURERS No.

*16.10.41. Rec'd from North American Aviation*



