

AJ 850

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

✓

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|---------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | loprash | | | | 91.45 | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL | DATE SERV. |
|---------|----------|---------------|------|------------------|------|----------------------|-------------|-----------|------------|
| 15.1.42 | "A" | Swift Current | 1830 | 3957 JSsA642 | 15/1 | 96 Phelps A | 1 | WRITE OFF | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 1 - Eng. installed Wasp SEH-1 - 11401/213682
 a/c 914 collided with 'e 850 as pilot of 914 failed to insure clear landing

