

AJ 960

HARVARD II

ATR II

1942

S E TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
31.3.44	Repair	Aircraft Repair				1.6.44	#4.T.C

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

31.3.44 allotted to Aircraft Repair. Almost Time Exp. & failure for overhaul

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

## AIRCRAFT RECORD CARD

FIRST ENTRY AT *No. 4 S.L. #39 S.F.T.S.* DATE *14.1.42* TRANSFER ORDER No. *13454*

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>31.3.44</i>	<i>Aircraft Repair Bldg.</i>	<i>T.O. F52.</i>			
<i>7.6.44</i>	<i># 4 T. C.</i>	<i>T.O. 13598</i>			
<i>1-12-44</i>	<i>NO. 2 A.C.</i>	<i>T.O. 17328 (30)</i>			
<i>11.4.45</i>	<i>Stored Reserve #2 AC</i>	<i>T.O. 12240</i>			
<i>16-10-45</i>	<i>NO. 2 A.C.</i>	<i>T.O. 15358</i>			
<i>2.1.46</i>	<i>NO. 2 A.C. - SR</i>	<i>T.O. mc16124</i>			
<i>11/2/46</i>	<i>Capitmc Remb Daughin</i>	<i>TO. mc16258</i>			
<i>10/4/46</i>	<i>War Assets</i>	<i>TO MC/3004</i>			

REMARKS *7-7-45:- STORED RESERVE - FROZEN SERIES**7.1.46: Converted from Standard to Wireless Type.*

*This since new - 3271.40*  
*oth - 679.30*

*U.K. contribution**10040/5348*

ENGINE TYPE	WASP S3H-1	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH		LEDGER FOLIO		SPECIFICATION No.	
REGISTRATION No.	AJ 960	MAKE & MODEL	HARVARD II	YEAR	1942	TYPE	S-E TRAINER
			ATR II			MANUFACTURERS No.	