

FE 874

HARVARD 118

1943

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|---------|----------|-----------------|-----------|------|-----------------|----------------|-----------|
| 26.7.44 | B" crash | Aircraft Repair | | | | 14.10.44 | S. R 44TC |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | No. IN CREW | DISPOSAL | DATE SERV. |
|------|----------|-------|------|------------------|------|----------------------|-------------|----------|------------|
| 1 | | | | | | | | | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

REMARKS:

RECORD OF WRITE-OFF

| APPLICATION RC'D FROM | DATE | FILE No. | DATE APPROVED | APPROVED BY | APPROVAL SENT TO | DATE | T. O. No. |
|-----------------------|------|----------|---------------|-------------|------------------|------|-----------|
| | | | | | | | |

DISPOSAL PARTICULARS

| | |
|--------------------------------|----------------------------|
| AIRFRAME | T. O. No. |
| ENGINE/S (QUOTE SERIAL NOS.) | T. O. No. |
| AIRSCREW/S (QUOTE SERIAL NOS.) | |
| ACCESSORIES | |
| REMARKS: | EFFECTIVE DATE WRITTEN-OFF |

AIRCRAFT RECORD CARD

| FIRST ENTRY AT <i>Stored Reserve 1426</i> | DATE <i>22.2.43</i> | TRANSFER ORDER No. <i>5759</i> | | | |
|---|---|--------------------------------|------|----|-----------|
| TRANSFERS | | TRANSFERS | | | |
| DATE | TO | AUTHORITY | DATE | TO | AUTHORITY |
| <i>27.10.43</i> | <i># 4 TC</i> | <i>TO 4904</i> | | | |
| <i>26.7.44</i> | <i>Aircraft repair</i> | <i>TO F-865</i> | | | |
| <i>14.10.44</i> | <i>Stored Reserve # 4 TC</i> | <i>TO 16479</i> | | | |
| <i>1.12.44</i> | <i>Stored Reserve No. 2 A.C.</i> | <i>TO 17328(21)</i> | | | |
| <i>14.7.45</i> | <i># 2 a.c.</i> | <i>TO 13726</i> | | | |
| <i>11.12.45</i> | <i>Opdalmc 10 RD (35 FTS)</i> <i>10 R.D.</i> | <i>TO MC15877</i> | | | |
| <i>2 OCT 46</i> | <i>WAR ASSETS</i> | <i>TO MC13049</i> | | | |

REMARKS

Line since new - 1098
" " " " " " - 118

| | | | |
|------------------------------------|---------------------------------|--------------------------------------|------------------------|
| ENGINE TYPE <i>WASP R1340-AN-1</i> | UNITS <i>1</i> | AIRSCREW TYPE (CODE) | REF. No. |
| BATCH No. | QUAN. IN BATCH <i>USA 138</i> | LEDGER FOLIO <i>713-Misc-USA 138</i> | SPECIFICATION No. |
| REGISTRATION No. <i>FE 874</i> | MAKE & MODEL <i>HARVARD 11B</i> | YEAR <i>1943</i> | TYPE <i>SE TRAINER</i> |
| | | | MANUFACTURERS No. |

SOLD