

AM 886

HUDSON V

(WRITE-OFF)

1941

T E BOMBER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
25.10.41	"A"	Franklin City N.Y. State	1520	31010-X109A57	26/10	P/O R.D. McLaughlin	2	Write-off	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc. 1: No. 3 I b SP147, 26.10 advised time of accident. Cause of crash unknown. Crew members P/O August Nowosad, observer, Sgt Douglas Roy Hill, wireless, and pilot killed. Engines installed 2 Wasp S3C4G - nos - 8308/203778, 8597/203890.

REMARKS:

Involved in major crash 25/10/41 at Tupper Lake, NY USA  
 subsequently salvaged by ...

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
#6 RD	11.12.41	1300-AM-886	6.3.42		Wk. Res. #6 RD	16.3.42	15342

DISPOSAL PARTICULARS

AIRFRAME	To be reduced to spares and produce	T. O. No. 15342
ENGINE/S (QUOTE SERIAL NOS.)	8368 / 203778, 8597 / 203890	T. O. No. 15342
AIRSCREW/S (QUOTE SERIAL NOS.)		
ACCESSORIES		

REMARKS:

auth. for write-off on 1300-AM 561.

EFFECTIVE DATE WRITTEN-OFF

30.3.42

AIRCRAFT RECORD CARD

FIRST ENTRY AT EAC # 310TU DATE 13.11.41 TRANSFER ORDER No. 12240

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
24.11.41	#6 RD Trenton (W. Res)	T.O. 12240			
16.3.42	Reduce to spares & produce	T.O. 15342			

REMARKS

ENGINE TYPE	MASP S306	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH		LEDGER FOLIO		SPECIFICATION No.	
REGISTRATION No.	AM 886	MAKE & MODEL	HUDSON V	YEAR	1941	TYPE	T E BOMBER
		(WRITE-OFF)				MANUFACTURERS No.	