

BW 705

HUDSON III

50 LA
MAKE & MODEL

1942

T E BOMBER

REGISTRATION No.

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | | | | | | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | No. IN CREW | DISPOSAL | DATE SERV. |
|------|----------|-------|------|------------------|------|----------------------|-------------|----------|------------|
| 1 | | | | | | | | | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Lined area for recording aircraft remarks.

REMARKS:

RECORD OF WRITE-OFF

| APPLICATION RC'D FROM | DATE | FILE No. | DATE APPROVED | APPROVED BY | APPROVAL SENT TO | DATE | T. O. No. |
|--------------------------------|------|----------|---------------|-------------|------------------|------|----------------------------|
| DISPOSAL PARTICULARS | | | | | | | |
| AIRFRAME | | | | | | | T. O. No. |
| ENGINE/S (QUOTE SERIAL NOS.) | | | | | | | T. O. No. |
| AIRSCREW/S (QUOTE SERIAL NOS.) | | | | | | | |
| ACCESSORIES | | | | | | | |
| REMARKS: | | | | | | | EFFECTIVE DATE WRITTEN-OFF |

AIRCRAFT RECORD CARD

| FIRST ENTRY AT | <i>E.A.C.</i> | DATE | <i>18.3.42</i> | TRANSFER ORDER No. | <i>18490</i> |
|----------------|--------------------------------|-------------------|----------------|--------------------|--------------|
| TRANSFERS | | | TRANSFERS | | |
| DATE | TO | AUTHORITY | DATE | TO | AUTHORITY |
| <i>22-5-44</i> | <i>Stored Reserve EAC</i> | <i>T.O. 13461</i> | | | |
| <i>9-8-44</i> | <i>Stored Reserve EAC</i> | <i>T.O. 15370</i> | | | |
| <i>25-8-44</i> | <i>Stored Reserve EAC</i> | <i>T.O. 15436</i> | | | |
| <i>22-3-44</i> | <i>E.A.C. (#12184)</i> | <i>T.O. 19486</i> | | | |
| <i>23.7.45</i> | <i>Stored Reserve EAC</i> | <i>T.O. 13959</i> | | | |
| | SR MC 6 REMU TO MC15886 | | | | |
| <i>9.1.46</i> | <i>Opdelmc 6REmdl</i> | <i>TOmc/6126</i> | | | |
| <i>22</i> | <i>Naval 46 War Assets</i> | <i>To MC13222</i> | | | |
| | | | | <i>D/N 4/1365</i> | |

REMARKS *25/8/44:- FROM B.C.A.T.P. TO W.H.O.*

Time since new : 971:50
o/H : NIL

lease-hold

| | | | | | | | |
|------------------|--------------------------|--------------|-------------|----------------------|------------------|-------------------|--|
| ENGINE TYPE | <i>W.P. CYCLOP 6205A</i> | UNITS | <i>2</i> | AIRSCREW TYPE (CODE) | | REF. No. | |
| BATCH No. | QUAN. IN BATCH | LEDGER FOLIO | | SPECIFICATION No. | | | |
| REGISTRATION No. | MAKE & MODEL | YEAR | <i>1942</i> | TYPE | <i>TE BOMBER</i> | MANUFACTURERS No. | |