

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
24.12.42	"B" Crash	H. R. D. Leonard					
24.1.44	"B" Crash	H. R. D. (W. Res)				30.10.43	E. A. C.
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
22.12.42	"B"	Debert Aerod	1150	310TUSA846	22/12	Sgt J. Wilson	3	Clark Base	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

Re 9.1.43 - Re-allotted to Clark Base for 9h + repairs, 5/1/43  
 Re Acc. 1 - Engine inst. 51301/41-44217, 12139/41-14032, Engine failed,  
 due to freezing and failing to take-off from end of runway  
 1.13.43 - Allotted E.A.C. from Clark Base to C. after repair

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
	12.3.44	11-1-4		#4 R.D.	#4 R.D. (W. Res)	16.5.44	4/50

DISPOSAL PARTICULARS

AIRFRAME <i>Written off.</i>	T. O. No. 4/50
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF 16.5.44

AIRCRAFT RECORD CARD

FIRST ENTRY AT		TRANSFERS	DATE	TRANSFER ORDER No.	
EAC		#31 (O.T.W)	29.9.42	3117	
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
24.12.42	W. R. D. Leander (W. Res)	To A 683			
5.1.43	Clark Ruse a/c	To A 1061			
30.10.43	E. a. C.	To 3193			
11.2.43	E. a. C.	To 5485			
24.1.44	#4 R. D. (W. Res)	To A 1061			
16.5.44	Write Off.	To 4/50			

REMARKS

ENGINE TYPE WASP R1830-67	UNITS 2	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.
REGISTRATION No. FK 399	MAKE & MODEL HUDSON VI (WRITE-OFF)	YEAR 1942	TYPE T E BOMBER
		MANUFACTURERS No.	