

FM173

LANCASTER X

M.E. BR. LANDPLANE

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
29/4/501	overhaul M.P. 201-1	W. J. Rae	CS 2501632			12.8.51	MCO
13.8.55	RM-25 Laminarization	876217/9 W. J. Rae	810 W476914				
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Mod. A.M. 426. Fitted - (Dual Controls)

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. NO.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.G.A.F. E. 293D 5M-1-44 (2801) H.Q. 885 E-233 - K.P. 99559

AIRCRAFT RECORD CARD

FIRST ENTRY AT *MC #1 (12150) (Q.V. Rec)* DATE *21 Aug 46* TRANSFER ORDER No. *MC 12685*

TRANSFERS

TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>29 Apr 50</i>	<i>D. 12150 (a.v. Rec)</i>	<i>10-1053</i>			
<i>12 May 51</i>	<i>M. 2150 (2070 4054)</i>	<i>701588</i>			
<i>13 Apr 55</i>	<i>12150 (1801) (Q.V. Rec) (a.v. Rec)</i>	<i>210-842</i>			

REMARKS:

21 Aug 46: Received from the Mutual Aid Board

V346129
V346280
V346200
V347299

ENGINE TYPE	<i>Merlin 224</i>	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.
<i>FM173</i>	<i>LANCASTER X (Mk) General (No. 1) (No. 2) (No. 3)</i>		<i>M.E. BR. LANDPLANE</i>	