

FM213

LANCASTER X

M.E. BR. LANDPLANE

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
12 Oct 1	rework of motor & repairs as necessary	De Naw	6501632			8-11-51	Man Exp.
20 Aug 52		De Naw	511965			23 July 53	Mac
26 Jul 55	for replacement of	Travis A	376818			11 Jan 57	MAC
11 Jan 57	for installation of AP-33 EO-05-15A-1A76	Travis A	572820				
5	check & secure of hose and						
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
15 Jan 52	B	6		6RAT107	16 Jan				
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME

T. O. No.

ENGINE/S (QUOTE SERIAL NOS.)

T. O. No.

AIRSCREW/S (QUOTE SERIAL NOS.)

ACCESSORIES

REMARKS:

EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 293D — 5M-1-44 (5801) H.Q. 885 — E-293 — K.P. 99359

## AIRCRAFT RECORD CARD

FIRST ENTRY AT

*MC #1610 (A.V. Roe)*

DATE

*21 Aug 46*

TRANSFER ORDER No.

*MC 1268*

TRANSFERS

TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>12 Oct 50</i>	<i>12 TSU (de Hav)</i>	<i>TO 1338</i>			
<i>6 Nov 51</i>	<i>WR 6 AD</i>	<i>TO 1508</i>			
<i>30 Mar 52</i>	<i>WR 6 AD</i>	<i>TO 1508</i>			
<i>20 Aug 52</i>	<i>12 TSU (de Hav)</i>	<i>QTO-1385</i>			
<i>23 July 53</i>	<i>MAC</i>	<i>QTO-1286</i>			
<i>11 Oct 53</i>	<i>624 P8 (Rocheliffe) 9773</i>	<i>QTO-1542</i>			
<i>20 Oct 53</i>	<i>MAC 15</i>	<i>QTO-1558</i>			
<i>26 Jul 55</i>	<i>11 TSU (Gannet A) 62</i>	<i>TO 719</i>			
<i>30 Jul 55</i>	<i>MAC (Stn Torbay)</i>	<i>TO 719</i>			
<i>11 Jan 57</i>	<i>11 TSU Gannet A 62</i>	<i>Q10756</i>			
<i>11 Jan 57</i>	<i>MAC Stn Torbay</i>	<i>Q10756</i>			

REMARKS:

*21 Aug 46 - Received from the Mutual Aid Board.*

346194  
346178  
345984  
346191

ENGINE TYPE

*Merlin 224*

UNITS

AIRSCREW TYPE (CODE)

REF. No.

BATCH No.

QUAN. IN BATCH

LEDGER FOLIO

SPECIFICATION No.

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

FM213

LANCASTER X

*MR.**MAC*

✓

M.E. BR. LANDPLANE

FM 213

LANCASTER  
10MPMERLIN  
224-5344765  
343413  
346178  
345616157-1  
077 (Proceed)  
241-0  
124-1

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS NO.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
11 Jan 57	756	MAC Sta Torbay			
9 June 58	306	Fairy Aviation ER			
9 June 58	306	107 R Unit Torbay			
22 Feb. 60	1016	11 Tsu Fairy Av. - CR			
22 Feb. 60	1016	MAC: 107 R U Torbay			
22 Oct 63	ATO 562	16 RD Summerville for <del>ATO</del>			
		*1/E			
30 Jun 64	ATO 372	CADCA / Royal Canadian Legion Branch #109 Godwin Ontario			
					ME 2592.

Configuration to 10MP auth Log 2606 18 Aug 59.

## OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
11 Jan 57	756	Fairley A 572820	for installation of APS33, LO-05-25A-6A176; search + search + locate + marking to include 0300 and 70 of check 27 385 6 May - included P400.
9 June 58	306	Fairley A 772816	for prototyping of removal of LCR-522 and replacement with 1CA67VHF
22 Feb. 60	1016	Fairley AV. 772816	for repairs and replacement of Telecons wiring in following systems interior systems, PAN 6 Radio Compass, PAN 7 Loran trans. (Dual LCR 67-UHF)