

KB 937

LANCASTER X LANDPLANE

10MR

1945

M.E. BOMBER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
5-7-51	mod to Ppe 101-25/100 reconditioning to 101-1	A. J. New	50501632				
25-9-51	major inspection engine checked necessary parts replaced - 100MR	label A. J. New	Page 16-267 cost 54965			16-10-52	5A 25/100
5 MAR 53	spec 101-25						
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

16-4-52 - interim 105.
16-10-52 - approximately 2 months.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. NO.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 233B — 3M-5-42 (2220) H.Q. 895 — E-233

AIRCRAFT RECORD CARD

FIRST ENTRY AT		DATE	TRANSFER ORDER No.
C.A.C. Halifax		28.6.45	13501
TRANSFERS		TRANSFERS	
DATE	TO	DATE	TO
11.9.45	Stored Reserve # 2 A.C.	31 Jan 55	11TSU (Mainly A) B Co
	SR MC 4SEHU	31 Jan 55	MAC
	104 REMS		
50 Apr 51	77012734 (De Hav)		
25 May 51	WR 6 R		
16 Apr 52	F-6 (AAS)		
30 Jun 52	SR 25 A MB		
14 Jul 52	UE 25 A MB		
18 Oct 52	UE 6 R		
19 Jan 53	SR 6 R		
13 Mar 53	12TSU (De Hav)		
21 Dec 53	MAC		

REMARKS:

28.6.45 This aircraft received from # 6 BR Group overseas.

Purchased.
 346054-90-879
 346204-90-884
 346224-90-1314
 346602-130-0

ENGINE TYPE	MERLIN 224	UNITS	4	AIRSCREW TYPE (CODE)		REF. No.	1
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO		SPECIFICATION No.			
REGISTRATION No.	MAKE & MODEL	YEAR		TYPE		MANUFACTURERS No.	
KB 937	LANCASTER & LANPLANE	1945		ME. BOMBER		MAC	

