

KB972

LANCASTER X (LANDPLANE)

1948

M E BOMBER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
14.12.51	recond to 19/11/25	De Shaw	W501632				
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME

T. O. No.

ENGINE/S (QUOTE SERIAL NOS.)

T. O. No.

AIRSCREW/S (QUOTE SERIAL NOS.)

ACCESSORIES

REMARKS:

EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 233B - 1M-1.43 (3029) H.Q. 885 - E-233

AIRCRAFT RECORD CARD

FIRST ENTRY AT *Eac, Halifax N.S.* DATE *28.6.45* TRANSFER ORDER No. *13507*

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>23.7.45</i>	<i>W.A.C.</i>	<i>T.O. 13914</i>			
<i>25.9.45</i>	<i>Stores Reserve 2 A.C.</i>	<i>T.O. 15101</i>			
<i>21.10.45</i>	<i>SR MC 4SEHU</i>	<i>T.O. 15888</i>			
<i>21.10.45</i>	<i>Salisbury 104 REMB</i>				
<i>10 May 45</i>	<i>WR 6 R L</i>	<i>T.O. 1084</i>			
<i>14 Dec 45</i>	<i>12750 (de Hav)</i>	<i>T.O. 1605</i>			
<i>31 Jan 52</i>	<i>CRD - strike off - burned</i>	<i>T.O. 1689</i>			

REMARKS:

*28/6/45 - THIS AIRCRAFT RECEIVED FROM No. 6 (BR) GROUP OVERSEAS.**25.9.45 - Serviceable**Purchased**343479**345885**343337**345836*ENGINE TYPE **MERLIN 224** UNITS **4** AIRSCREW TYPE (CODE)

REF. No.

BATCH No. QUAN. IN BATCH LEDGER FOLIO SPECIFICATION No.

REGISTRATION No. MAKE & MODEL YEAR TYPE MANUFACTURERS No.

K6972**LANCASTER 410118 (LANDPLANE)****1945****M E BOMBER***8/30/38/19*