

**OVERHAUL DATA**

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1	<i>Lub. trouble</i>				<i>870.05</i>		
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

**ACCIDENT RECORD**

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
<i>9.9.41</i>	<i>"C1"</i>	<i>High River aerod</i>	<i>0800</i>	<i>#597JS, T333</i>	<i>13/9</i>	<i>LAC G.B. Latimer</i>	<i>Solo</i>		
<i>28.2.42</i>	<i>"A"</i>	<i>Outlets Alta.</i>	<i>1045</i>	<i>5E7JS, T54</i>	<i>28/2</i>	<i>LAC F.D. Holtan</i>	<i>Solo</i>		
3									
4									
5									
6									
7									
8									

B. S. LTD.

**AIRCRAFT RECORD CARD**

PAT'D 1920

**REMARKS**

*Re. acc. 2: Eng. installed 85411/7499% went into spiral striking ground.*

