

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
23.2.43 <sup>1</sup>		#10 R.D.(W.R.)				12.7.43	#6 R.D.(W.R.)
21.4.43 <sup>2</sup>	Mech. failure	M.C. Whiston				12.7.43	#1 R.D.(W.R.)
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
9.1.42	"C2"	London Road	1115	32 EFTS SA140	9/1	Cpl. A.F. Brennan	Solo		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

Re acc. 1:- Tiger Moths 5061 and 5153 collided while taxiing.  
 Engine installed - Tiger Moths - no. 85560/7746.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE'S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREWS (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT # 4 T.C.			DATE 25.8.41	TRANSFER ORDER No. 2467		
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
23.2.43	# 10 P.O. Calgary (W. Res.)	T.O. 7-1295				
21.4.43	M.C. Aviation (Comp)	T.O. 7-88				
12.7.43	# 6 P.O. Brenton (W. Res.)	T.O. 2087				
24.8.43	# 1 T.C.	To 3222				
29.4.44	APDAM, # 1 T.C.	T.O. 15912				
30.1.45	(ip dal # 1 U.C.	T.O. 18177	17863	(C129A)		
23.1.46	Last Assets Corp.	To 18171				

REMARKS: HRS: PURCHASED  
 SINCE NEW: 824.30  
 SINCE OF HAND: N.A.  
 LOCATION: #102 A.H.U.

ENGINE TYPE	GIPSY MAJOR I	UNITS		AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	TP 2412	LEDGER FOLIO	1200-38-32	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.			
5153 ✓	TIGER MOTH I	1941	ELEM TRAINER				