

26098

TUTOR

J85-CAN-40

MANU No 1099

114098 "A"

Crash 22 Sep 79 Minot North Dakota

RCAP REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY ATLTSU CANADAIR

DATE 23 Feb 65

QTO No. 1003

CD No. 262022

TRANSFERS 1510-21-807-4601

TRANSFERS

DATE

QTO No.

TO

DATE

QTO No.

TO

DATE	QTO No.	TO	DATE	QTO No.	TO
23 Feb 65	QTO 1003	RCAPTS/AFed Minot	20/9/89	QTO 212	KX Moose Jaw 8058
14 May 69	QTO 153	RCAP Det M.V. (8042)	22/7/93	QTO 214	Strike off
6 Aug 76	QTO 177	Lt ANDERSON M.V. A/F			scrap
3 May 77	QTO 121	Ct 2 CFFTS Moose Jaw			ME 3277
16 May 77	QTO 132	Lt NWL Edmonton (8090)	13/10/93	QTO 270	KX Toronto
16 May 77	QTO 132	Ct 2 CFFTS Moose Jaw (8090)			Strike off
27 Sep 79	QTO 251	KX Moose Jaw 8129			
16 Oct 80	QTO 214	CX 2 CFFTS M. Jaw			
3 Jan 84	QTO 311	LX 402 NW 2 8053			
3 Jan 84	QTO 311	CX 2 CFFTS M. Jaw 8053			
5/2/88	QTO 318	LX 402 NW 2 8058			
5/2/88	QTO 318	CX 2 CFFTS M. Jaw 8058			

DAM442504 082100Z Jan 71 authorizes new registration number.

## OVERHAUL DATA

DATE	QTO NO.	CONTRACTOR	REPAIRS
22 Jul 68	T1271	A.M. Dunbar	Released on completion W4FT: Recat heat installation
16 Aug 76	Q70177	L.A. Dunbar	M.V. W6 NW 27 To be brought up to AG status
14 May 77	Q70132	NW Edmiston	C032404 modifications
3 Jan 84	QT0311	LX 402 NW 2	for conversion to the snowbird role CDW 2792825
5/2/88	OT0318	LX 402 NW 2	for Comm and AC heater 2795825