

26110

TUTOR

J85 -CAN-40

MANUF No 1110

114110 A crash 3/9/89

RCAP REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT IITSU CANADAIR

DATE 8 June 65

QTO No. 279

CD No. 262022

TRANSFERS

1510-21-807-4601

TRANSFERS

DATE

QTO No.

TO

DATE

QTO No.

TO

8 June 65	QTO 279	TC-ETS/AFS Genli	29-10-82	QTO 262	CX 431 ⁸²¹⁹ moose jaw
25 Mar 69	QTO 581	PA AMDU Det 710 ⁽⁸²²⁷⁾	19/11/87	QTO 276	LX 402 NWD ⁸²⁰⁶
16 Aug 76	QTO 177	LX AMDU Det N.V. 4/8	19/11/87	QTO 276	CX 431 ⁸²⁰⁶ moose jaw
6 Apr 77	QTO 102	CT 2 CFFTS ⁽⁸²²⁰⁾ moose jaw	8/6/88	QTO 0172	LX NWD 8137
18 May 77	QTO 132	LX NW/Edmonton ⁽⁸²²⁰⁾	8/6/88	QTO 0172	CX 431 ⁸¹³⁷ moose jaw
18 May 77	QTO 132	CT ⁸⁵⁴⁰ CCFTS ⁽⁸²²⁰⁾ moose jaw	22/12/88	QTO 307	LX NWD 8137
name changed 1978		CX 431 (AD) ⁽⁸¹³⁷⁾ moose jaw	22/12/88	QTO 307	CX ⁽⁴³¹⁾ moose jaw
1 Dec 80	QTO 246	LX AMDU ⁸⁰⁶⁸ Hunter	20/9/89	QTO 212	KX ⁸¹³⁷ moose jaw
1 Dec 80	QTO 246	CX 431 ⁸⁰⁶⁸ moose jaw	22/7/93	QTO 214	Strike off
7 Oct 81	QTO 239	LX 451 BAL ⁸⁰³⁹	13/10/93	QTO 270	scrap
7 Oct 81	QTO 239	CX 431 ⁸⁰⁶⁸ moose jaw		KX Toronto	ME 3277
29-10-82	QTO 262	LX 451 BAL		Strike off	

DAM442504 082100Z Jan 71 authorizes new registration number.

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
16 Aug 76	QTO 177	HANDWORTH WGMU25	To be brought up to +G status
18 May 77	QTO 132	NW1 C103624014	modification
14 Dec 80	QTO 246	LX AMDL Juntor	for painting L/H wing in snowbird colours Project E 04096A
7 Oct 81	QTO 239	LX 401 BAL 2790825	for painting to snowbird colour scheme
29-10-82	QTO 262	LX 401 BAL 2790825	for touch up painting under warranty
19-11-87	QTO 276	LX 402 NW2	Comm and AC Inverter mod 2795825
8/6/88	QTO 172	LX NW2	for avionics drawing package validation ^{MCO/01-BF} W84757
22/12/88	QTO 307	LX NW2	for statement of work PWO/402/NW2/023/88 (ties CD)