

26132

TUTOR

J85-CAN-40

MANUF No 1132

114132**'A' Crash 24 Jan 77**

RCAP REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT 11TSU CANADAIR

DATE 30 Sep 65

QTO No. Q10507

CD No. 262022

TRANSFERS

TRANSFERS

DATE

QTO No.

TO

DATE

QTO No.

TO

30 Sep 65	Q10507	TC 2FTD Moose Jaw	28 Jan 77	Q10307	Rx CFB Moose Jaw 41E
25 Mar 66	Q10837	IR 6 RC int-sec			involved in air accident
12 Dec 67	Q10502	AR AMDU Det mt view	24 Aug 78	Q10183	Strike Off 4' Cat
4 Apr 68	Q10106	AR AMDU Det mt view			<u>Crash 24 Jan 77</u>
11 June 68	Q10215	WR AMDU Inerton (8078)			W/E 8145
11 June 68	Q10215	TC 1FTD Simla (8078)			
9 Oct 69	TC 81010	TC 2FTD Moose Jaw (8136)			
30 Jul 70	AL4404482-2	^{effective 23 July 70} TC 26FFTS Moose Jaw			
28 Oct 70	Q10400	bandaw mtl (8201)			
28 Oct 70	Q10400	TC 26FFTS Moose Jaw (8201)			
26 Mar 76	C10379	Lt Col Ed Edmister (8018)			
26 Mar 76	Q10379	CT 2CFFTS Moose Jaw (8018)			

DAM442504 082100Z Jan 71 authorizes new registration number.

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
11 June 68	Q10215	WRANDU WMFT	Recent heat installation
28 Oct 70	Q10400	Edwards AL2 Rep #2 to 80572673	Phase 2 of 88P-234 and PWO A-507 dated 30 Sep.
26 Mar 76	Q10379	NWcl. C103624014	modification