

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Taxiing. towards hargar cufter OR COMMANDING OFFICER'S REPORT: authorized instrument flying. DATE: 22-11-42. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Student pilot taxied into F/O COMPOSITION: Greanhalgh walking on tarmac. F/L Sharpe, E.W.C. (C2797) 2 T.C.H.Q. Admin, Unit, R.C.A.F.. Winnipeg. RECOMMENDATIONS: PUBLICATION PERIODICALLY IN UNIT, D. R. C. 'S A WARNING THAT ALL PERSONNEL WALKING WITHIN AREAS IN WHICH NC NORMALLY TAXI, MUST BE EXPECIALLY ON GUARD FOR SUCH NC, AND THAT ALL PERSONNEL WHOSE DUTIES REQUIRE THEM PRIMARY CAUSE: TO WALK ON THE APRON OR ANY OTHER AREA WITHIN WHICH A/C ARE BEING TAXIED, SIGN A CERTIFICATE MONTHLY THAT EACH HAS KEPT A CAREFUL LOOK-Pedestrain walking on apron failed OUT FOR TAXIENG A/C WHILE WALKING WITHIN SUCH AN AREA-) to observe an A/C being taxied in a continuously turning movement onto Not concurred in by A.C.C. and along the apron towar, and. ACTION TAKEN: eventually behind him and that (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil. he could probably be continuously CONCLUSIONS OF A.IB. in its blind spot while taxiing. Agree with the findings and with the remarks of the A.O.C. with respect to the monthly signing of certificates. It is not considered that any blame should rest SECONDARY CAUSE OR CONTRIBUTING FACTORS: with the pilot for this accident. A/C struck pedestrain while taxiing. RECORDED BY DATE CHECKED BY DATE R.C.A.F. FORM L20 REQ, 1247 10M-15-11-41