

ACCIDENT CLASSIFICATION

UNIT 117 (BR) North Sydney	COM. E	PLACE Near Sable Island	DATE 4-10-43	TIME
A/C TYPE CATALINA IV	NO. JX207	CRASH CAT. "D"	H.Q. FILE 1300-JX207	
			S.E.	M.E. X
			DAY	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Boucher, D.A.	F/O	J26028	CAPT	Uninj.	NO. DATE
Hostein, K.M.	SGT	R152231	2nd P	Uninj.	
Dickey, E.D.	F/O	J11500	NAV	Uninj.	D 14 (REVISED) NO. CHECKED
Campbell, B.D.	WO2	R111898	WAG	Uninj.	
Elgear, D.	F/S	R102410	WAG	Uninj.	4 #2
Rosall, W.G.	SGT	R153318	WAG	Uninj.	
Muchulsky, P.P.	SGT	R107365	Eng	Uninj.	
Phillips, H.M.	F/S	10662	Eng	Uninj.	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
P & W R1830-92				SOLO	DUAL	SOLO	DUAL
	41743-B/21510	Nil					
	41730-B/21497	Nil					

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJURY
3RD
5

RAF
M
N

PURPOSE OF FLIGHT:

Sweep.

TECHNICAL OFFICER'S REPORT:

Nil 1400/1955

NATURE OF ACCIDENT:

While on patrol a/c struck a geyser of water caused by swell breaking over reef.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil